

# Proposed amendment to Appendix 10 to the GCU

# **Record of amendments**

Amended by	Date	Module	Amendment
WG Neandertal	05/09/2023	M04.003	First draft
WG MNT decision	09-10/04/2024	M04.003	Update
WU SG decision	14/05/2024	M04.003	Approved by WU SG
GCU JC decision	04/06/2024	M04.003	Approved by GCU JC after minor rewordings

Title	M04.003 Replace earthing straps M04.003 Remplacer la tresse de masse M04.003 Erdungsseil ersetzen		
Proposed amendment made by RU/keeper/other:	WG Neandertal		
Proposed amendment to:	GCU Appendix 10 GCU Annex 6 (Appendix 10)		
Proposer:			
Location, date:	05/09/2023		
Concise description:			

#### 1. Starting point (current situation):

#### 1.1. Introduction

The task of the working group for the modularization of appendix 10 of the GCU is to describe new modules containing the measures to restore fitness to run and to create a link to the damage codes of appendix 9 as well as to the coding of the works of appendix 10 annex 6

#### 1.2. Mode of operation

The results of the working group are submitted as amendment to the working group appendix 10 and so introduced in the regular process for validation of amendments

#### 1.3. Anomaly/description of problem

Appendix 10 does not currently provide a comprehensive package of works to be carried out in order to restore the fitness to run. By introducing modularisation, this problem is solved. Modularisation supports the further digitalisation.

#### 1.4. Does this concern a recognised code of practice\* (e.g. ISO, EN)?

$\boxtimes$ No	Yes	(state which)	):

#### 2. Target situation

#### 2.1. Elimination of anomaly/problem (solution sought)

See below point 3

#### 3. Additional text (relates only to proposed amendments to GCU Appendix 10)

Colour codes for amendment proposals:

Black: Currently applicable text; provides information and remains unchanged

Red: New text

Blue: (may be crossed out): Text to be deleted

Symbols are used as follows:

→ Link to other section of the GCU

Documentation of the work acc. to app. 10 annex 6

Note: if changes of the annex 6 are required, they have to be named below.

The damage codes of section 2 of this amendment proposal will be updated in the three languages in table in the introduction.

AP-MNT-2024-15

<sup>\* &</sup>quot;a written set of rules that, when correctly applied, can be used to control one or more specific hazards." (Source: Regulation (source: Regulation EC 402/2013, Article 3)

<sup>&</sup>quot;Technical provisions laid down in writing or conveyed verbally and pertaining to procedures, equipment and modes of operation which are generally agreed by the populations concerned (specialists, users, consumer and public authorities) to be suitable for achieving the objective prescribed by law, and which have either proven their worth in practice or, it is generally agreed, are likely to within a reasonable period of time". (Source: BMJ Handbuch der Rechtsförmlichkeit – guide published by German Ministry of Justice)

Damage code Appendix 9	Measures to restore the fitness to run
4.6.2.2 All earthing straps ineffective, fastening points indicate that straps should be present	M04.003 Replace earthing strap
ilidicate that straps should be present	
Code d'anomalie Annexe 9	Mesures pour rétablir l'aptitude à la circulation
4.6.2.2 Toutes les tresses de mise à la masse sont inefficaces, les points de fixation permettent de déterminer la présence de tresse(s)	M04.003 Remplacer la tresse de masse
Schadcode Anlage 9	Maßnahmen zur Wiederherstellung Lauffähigkeit
4.6.2.2 Alle Erdverbindungen sind unwirksam (Befestigungspunkte lassen erkennen, dass Erdverbindungen vorhanden sein müssen	M04.003 Erdungsseil ersetzen

#### ΕN

## M04.003 Replace earthing straps

Tech	nnical requirements:	-
Orga	nisational preparations:	-
No.	Work tasks, technical target state and additional notes	
1.		g or damaged earthing straps: nust be corrosion-free and cleaned nust be complete

## FR

## M04.003 Remplacer la tresse de masse

Con	ditions techniques :	-
Mes	ures préparatoires :	-
n°	Contenu de l'intervention, état technique théorique et autres indications	
1.	Identifier et remplacer les tresses de masse manquantes ou avariées :	
		ntact doivent être exemptes de corrosion et nettoyées. s doivent être entièrement réalisés

#### DE

# M04.003 Erdungsseil ersetzen

Technische Voraussetzungen: Organisatorische Vorbereitungen:		-	
			Nr.
1.	Fehlende oder defekte Erdungsseile identifizieren und ersetzen:  • Kontaktflächen müssen korrosionsfrei und gereinigt sein  • Schraubverbindungen müssen vollständig hergestellt sein		

#### 4. Reason:

Transforming the measures of GCU Appendix 10 into the new modular design

## 5. Assess potential positive/negative impacts

Assess the possible positive and negative effects (operations, costs, administration, interoperability, safety, competitiveness, etc.) on a scale of 1 (very low) to 5 (very high):
Reasoning behind amendment:

This measure describes the good practice in maintenance and should not have a positive or negative effect on operations, costs, administration, interoperability, competitiveness, but presents an increase on safety.

# 6. Safety appraisal of proposed amendment

Description of actual/target system, and scope of change to be made (see points 1 and 2).

Performance of risk analysis is unnecessary where only recognised standards are implemented.

Risk analysis conducted by:

6.1.	Does the change have an impact on safety?	⊠No ☐ Yes
Reas		
6.2.	Is the change significant?	⊠No ☐ Yes
Reas	on: No change in the process	
6.3.	Determining and classifying risk	⊠ N/A
6.3.1.	Effect of change in normal operation:	
6.3.2.	Effect of change in the event of disruption/deviation from normal operation:	
6.3.3.	Potential misuse of system:	
	□ No	
	Yes (describe possible misuse):	
6.4.	Have safety measures been applied?	⊠No ☐ Yes
	ach type of risk, one of the following risk acceptance criteria is to lected:	
•	Code of practice	
•	Use of reference system	
•	Explicit risk assessment	
6.5.	Has a risk analysis been submitted to the assessment body?	⊠No ☐ Yes
Asses		
Attacl	[Appendix]	